



PROVINCIA DI BOLZANO 3+ lavoratori

## **MED98866**

## REINTEGRATION FIRST-AID BOX COMPL.

Medication package designed for companies or manufacturing units of group A and B and in any case with three or more workers. Content according to DM 388/2003 annex 1 and D.L. 81/2008 art.45 and D.P.P. 25/2005, Regulation on first aid provisions in companies of the Autonomous Province of Bolzano, which supplements the minimum content required by the national decree. For group A companies, the content provided for in annex 1 is to be integrated on the basis of the risks present in the workplace. complete with:

- 5 pairs of disposable sterile gloves;
- 1 anti-squirt visor;
- 1 litre of cutaneous Povidone Iodine with 10% iodine for professional use;
- 1.5 litre of saline solution (sodium chloride 0,9%);
- 10 packages of sterile gauzes 10 x 10 cm single packaging;
- 2 packages of sterile gauzes 18 x 40 cm single packaging;
- 2 disposable sterile sheets;
- 2 disposable sterile medical forceps;
- 1 medium-sized elastic bandage;
- 1 package of hydrophilic cotton;
- 2 packages of various sized plasters ready-to-use;
- 2 rolls of high plaster 2,5cm;
- 1 pair scissors;
- 3 tourniquets;
- 2 packages of instant ice;
- 2 disposable sanitary waste bags;
- 1 thermometer;
- 1 sphygmomanometer:
- 1 stethoscope;
- 3 medication packages 8 cm;
- 3 medication packages 10 cm;
- 3 elastic edged bandage size 8 cm;

For further information and/or technical data related to the product, please refer to the Oscar Boscarol Company.



- 3 elastic edged bandage size 10 cm;
- 1 isothermal blanket;
- 1 protection handkerchief for artificial ventilation.
- 250 ml bottle of disinfectant;
- First Aid instructions:
- Copy of DM (ministerial order) 388/2003.

(Group A companies are those at high risk, such as thermoelectric power plants, nuclear plants and laboratories, mining companies, explosives factories, or companies/production units with more than 5 workers with high INAIL accident index or companies/production units with more than 5 permanent workers in the agricultural sector).

(Group B companies are those with 3 or more workers that do not fall into Group A, so they are not high risk).

(Group C companies are those with less than 3 workers that do not fall into group A, so they are not at high risk).

For further information and/or technical data related to the product, please refer to the Oscar Boscarol Company.