



## 1 o 2 lavoratori

## VAL45176

## SOUTH TYROL FIRST AID CASE

Medication case designed for companies or manufacturing units of group C (not classified as high risk), hence with less than three workers. Content according to DM 388/2003 attachment 2 and D.L. 81/2008 art.45 and D.P.P. 25/2005, Regulation on first aid provisions in companies of the Autonomous Province of Bolzano, which supplements the minimum content required by the national decree. Article 2 of M.D. 388/2003 establishes that the content in Annex 2 must be provided to workers who work in locations other than the company headquarters or production unit. Complete with:

- 2 pairs of disposable sterile gloves;
- 125 ml of cutaneous Povidone Iodine with 10% iodine;
- 250 ml of saline solution (sodium chloride 0,9%);
- 3 packages of sterile gauzes 10 x 10 cm single packaging;
- 1 packages of sterile gauzes 18 x 40 cm single packaging;
- 1 disposable sterile medical forceps;
- 1 package of hydrophilic cotton;
- 1 package of various sized plasters ready-to-use;
- 1 roll of high plaster 2,5 cm;
- 1 roll of elastic edged bandage height 10 cm;
- 1 pair scissors;
- 1 tourniquet;
- 1 package of instant ice;
- 1 disposable sanitary waste bags;
- 2 medication packages 8 cm;
- 2 medication packages 10 cm;
- 2 elastic edged bandage size 8 cm;
- 2 elastic edged bandage size 10 cm;
- 1 isothermic blanket;
- 1 protection handkerchief for artificial ventilation;
- First Aid instructions
- Copy of DM (ministerial order) 388/2003, annex 2.

For further information and/or technical data related to the product, please refer to the Oscar Boscarol Company.



- Dimensions: about 25.5x9x19.5 cm
- Weight: about 1.5 kg

(Group A companies are those at high risk, such as thermoelectric power plants, nuclear plants and laboratories, mining companies, explosives factories, or companies/production units with more than 5 workers with high INAIL accident index or companies/production units with more than 5 permanent workers in the agricultural sector). (Group B companies are those with 3 or more workers that do not fall into Group A, so they are not high risk). (Group C companies are those with less than 3 workers that do not fall into group A, so they are not at high risk).

For further information and/or technical data related to the product, please refer to the Oscar Boscarol Company.